



**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES  
LARGE AIRCRAFT**

**BIWEEKLY 2005-02**

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation  
Federal Aviation Administration  
Regulatory Support Division  
Delegation and Airworthiness Programs Branch, AIR-140  
P. O. Box 26460  
Oklahoma City, OK 73125-0460  
FAX 405-954-4104



## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency			
<b>Biweekly 2005-01</b>			
2004-22-25	COR	Boeing	767-200, -300, and -300F Series
2004-23-06	COR	Boeing	757-200, -200PF, -200CB, and 757-300 Series
2004-24-06		SAAB Aircraft AB	SAAB SF340A and SAAB 340B Series
2004-25-01		Gulfstream Aerospace LP	Gulfstream 100, Astra SPX, and 1125 Westwind Astra Series
2004-25-02		Airbus	A320-111, -211, -212, and -231 Series
2004-25-03	S 99-01-17	Airbus	A320-111, -211, -212, and -231 Series
2004-25-12	COR	EMBRAER	EMB-135 and -145 Series
2004-26-03	S 2001-23-02	Rolls-Royce plc	Engine: RB211-535E4-37, RB211-535E4-B-37, RB211-535C-37, RB211-535E4-B-75, RB211-535E4-C, and RB211-22B-02 Turbofan
2004-26-04	S 99-22-14	Pratt & Whitney	Engine: JT8D-209, -217, -217A, -217C, and -219 Turbofan
2004-26-05	S 97-07-04	Rolls-Royce plc	Engine: RB211-524B-02, -524B2, -524B3, -524B4, -524C2, -524D4, RB211-524G, and -524H Series
2004-26-06		Boeing	767-300 and 767-300F Series
2004-26-07		Airbus	A318-111, -112, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, and -231 Series
2004-26-08		Bombardier, Inc.	CL-215-6B11 (CL215T Variant) and CL-215-6B11 (CL415 Variant) Series
2004-26-10	S 2004-05-22	Rolls-Royce Deutschland (RRD)	Tay 611-8, Tay 620-15, Tay 620-15/20, Tay 650-15, Tay 650-15/10, and Tay 651-54 Turbofan
2004-26-12		EMBRAER	ERJ 170 Series
2005-01-01	S 2002-04-10	Airbus	A319 and A320-200 Series
2005-01-02		Lockheed	1329-23A, -23D, -23E, and 1329-25 Series
2005-01-03		Boeing	747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, 747SP and 747SR Series
2005-01-04	S 98-15-13	Raytheon Aircraft Company	65-90, 65-A90, B90, C90, C90A, C90B, E90, F90, H90, 100, A100, A100-1 (RU-21J), B100, 200, 200C, 200CT, 200T, A200, A200C, A200CT, B200, B200C, B200CT, B200T, 300, B300, B300C, 99, 99A, A99, A99A, B99, C99
2005-01-05	S 2004-09-15	EMBRAER	EMB-135 and EMB-145 Series
2005-01-06		Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325 Series
2005-01-07		Boeing	747-100 and -200B Series
2005-01-08		Airbus	A310, A300 B4-600, B4-600R, F4-600R, and C4 605R Variant F (Collectively Called A300-600), Series
2005-01-09		Boeing	747-100, -200B, -200F, -200C, -100B, -300, -100B SUD, -400, -400D, -400F, and 747SR Series
<b>Biweekly 2005-02</b>			
94-01-10 R2	R	Boeing	757-200 and -200PF Series
98-20-38 R1	R	Raytheon Aircraft Company	Beech 200 (A100-1 (U-21J)), Beech 200C, Beech 200CT, Beech 200T, Beech A200 (C-12A) or (C-12C), Beech A200C (UC-12B), Beech A200CT (C-12D), (FWC-12D), (RC-12D), (C-12F), (RC-12G), (RC-12H), (RC-12K), or (RC-12P), B200CT, and B200T
2005-01-12		Boeing	757-200, -200PF, and -200CB Series
2005-01-13		Boeing	767-300 Series
2005-01-15	S 2002-11-08	Rolls-Royce plc	Engine: RB211 Trent 875, 877, 884, 884B, 892, 892B, and 895 Series Turbofan
2005-01-16	S 2001-16-05	Rolls-Royce plc	Engine: RB211 Trent 768-60, Trent 772-60, and Trent 772B-60 Turbofan
2005-01-18	S 93-25-07	Raytheon Aircraft Company	A100-1 (U-21J), 200, B200, A200 (C-12A), A200 (C-12C), A200C (UC-12B), A200CT (C-12D), A200CT (FWC-12D), A200CT (RC-12D), A200CT (C-12F), A200CT (RC-12G), A200CT (RC-12H), A200CT (RC-12K), A200CT (RC-12P), A200CT (RC-12K), 200C, B200C, 200CT, 200T, B200C (C-12F), B200C (UC-12F), B200C (UC-12M), B200CT, 300, B300, B300C, and B300C
2005-01-19	S 2004-10-15	GARMIN International Inc.	Appliance: GTX 33, GTX 33D, GTX 330, and GTX 330D Mode S Transponders

**BW 2005-02**

**BOEING  
AIRWORTHINESS DIRECTIVE  
REVISION  
LARGE AIRCRAFT**

**94-01-10 R2 Boeing:** Amendment 39-13937. Docket No. FAA-2005-20009; Directorate Identifier 2003-NM-220-AD.

**Effective Date**

- (a) This airworthiness directive (AD) becomes effective January 28, 2005.

**Affected ADs**

- (b) This AD revises AD 94-01-10 R1, amendment 39-13247 (68 FR 48546, August 14, 2003).

**Applicability**

- (c) This AD applies to Boeing Model 757-200 and -200PF series airplanes, certificated in any category, equipped with Pratt and Whitney PW2000 series engines.

**Unsafe Condition**

- (d) This AD was prompted by a determination of an error in the existing AD. The Federal Aviation Administration is issuing this AD to prevent deployment of a thrust reverser in flight and subsequent reduced controllability of the airplane.

**Compliance**

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Inspections/Adjustments/Functional Checks/Modification**

- (f) For airplanes having line numbers prior to 442: Within 14 days after September 16, 1991 (the effective date of AD 91-20-09, amendment 39-8043), accomplish either paragraph (f)(1) or (f)(2) of this AD.

- (1) Accomplish both paragraphs (f)(1)(i) and (f)(1)(ii) of this AD:

- (i) Inspect the thrust reverser directional control valve (DCV) assemblies of both engines to determine the solenoid-driven pilot valve's part number, in accordance with Boeing Alert Service Bulletin 757-78A0027, dated September 9, 1991.

- (A) If any DCV has a suspect pilot valve as specified in the service bulletin, prior to further flight, replace the DCV with a DCV that has a part number of a non-suspect solenoid-driven pilot valve, in accordance with the service bulletin.

(B) If a DCV has a non-suspect solenoid-driven pilot valve as specified in the service bulletin, that pilot valve does not need to be replaced.

(ii) Perform all tests and inspections of the engine thrust reverser control and indication system on both engines in accordance with Boeing Service Bulletin 757-78-0025, dated September 9, 1991. Prior to further flight, correct any discrepancy found in accordance with the service bulletin.

(2) Accomplish paragraph (f)(1) of this AD on one engine's thrust reverser and deactivate the other engine's thrust reverser, in accordance with section 78-31-1 of Boeing Document D630N002, "Boeing 757 Dispatch Deviation Guide," Revision 8, dated January 15, 1991.

(g) For airplanes having line numbers prior to 442: Within 24 days after September 16, 1991, the requirements of paragraph (f)(1) of this AD must be accomplished on both engines' thrust reverser systems.

(h) For airplanes having line numbers prior to 442: Repeat the tests and inspections specified in paragraph (f)(1)(ii) of this AD at intervals not to exceed 3,000 flight hours, and before further flight following any maintenance that disturbs the thrust reverser control system. Correct any discrepancy before further flight in accordance with Boeing Service Bulletin 757-78-0025, dated September 9, 1991.

## **Installation/Functional Test**

(i) For airplanes having line numbers prior to 442: Within 5 years after March 3, 1994 (the effective date of AD 94-01-10, amendment 39-8792), install an additional thrust reverser system locking feature (sync lock installation), in accordance with Boeing Service Bulletin 757-78-0028, Revision 1, dated October 29, 1992; or Revision 2, dated January 14, 1993.

(j) For all airplanes: Within 1,000 hours' time-in-service after installing the sync lock required by paragraph (i) of this AD (either in production or by retrofit), or within 1,000 hours' time-in-service after March 3, 1994, whichever occurs later; and thereafter at intervals not to exceed 1,000 hours' time-in-service: Perform functional tests of the sync lock in accordance with the "Thrust Reverser Sync Lock Integrity Test" procedures specified below. If any discrepancy is found during any test, correct it before further flight in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; the corrective action in the Boeing 757 Maintenance Manual is one approved method.

### *"Thrust Reverser Sync Lock Integrity Test"*

#### **1. General**

A. Use this procedure to test the integrity of the thrust reverser sync locks.

#### **2. Thrust Reverser Sync Lock Test**

A. Prepare for the Thrust Reverser Sync Lock Test.

(1) Open the auto speedbrake circuit breaker on the overhead circuit breaker panel, P11.

(2) Do the steps that follow to supply power to the thrust reverser system:

(a) Make sure the thrust levers are in the idle position.

*Caution:* Do not extend the thrust reverser while the core cowl panels are open. Damage to the thrust reverser and core cowl panels can occur.

(b) Make sure the thrust reverser halves are closed.

(c) Make sure the core cowl panels are closed.

(d) Put the EEC Maint Power switch or the EEC Power L and EEC Power R switches to the Altn position.

(e) For the left engine:

(1) Put the EEC Maint Channel Sel L switch to the Auto position.

(2) Put the L Eng fire switch to the Norm position.

(f) For the right engine:

(1) Put the EEC Maint Channel Sel R switch to the Auto position.

(2) Put the R Eng fire switch to the Norm position.

(g) Make sure the EICAS circuit breakers (6 locations) are closed.

*Warning:* The Thrust Reverser will automatically retract if the electrical power to the EEC/Thrust Reverser Control System is turned off or if the EEC Maint Power switch is moved to the Norm position. The accidental operation of the Thrust Reverser can cause injury to persons or damage to equipment can occur.

(h) Make sure these circuit breakers on the main power distribution panel, P6, are closed:

(1) Fuel Cond Cont L

(2) Fuel Cond Cont R

(3) T/L Interlock L

(4) T/L Interlock R

(5) Left T/R Sync Lock

(6) Right T/R Sync Lock

(7) L Eng Electronic Engine Control Altn Pwr (if installed)

(8) R Eng Electronic Engine Control Altn Pwr (if installed)

(i) Make sure these circuit breakers on the overhead circuit breaker panel, P11, are closed:

(1) Air/Gnd Sys 1

(2) Air/Gnd Sys 2

(3) Landing Gear Pos Sys 1

(4) Landing Gear Pos Sys 2

(j) For the left engine, make sure these circuit breakers on the P11 panel are closed:

(1) Left Engine PDIU

(2) Left Engine Thrust Reverser Cont/Scav Press

(3) Left Engine Electronic Engine Control Altn Pwr (if installed)

(4) Left Engine Thrust Reverser PRI Cont

(5) Left Engine Thrust Reverser Sec Cont

(k) For the right engine, make sure these circuit breakers on the P11 panel are closed:

(1) Right Engine PDIU

(2) Right Engine Thrust Reverser Cont/Scav Press

(3) Right Engine Electronic Engine Control Altn Pwr (if installed)

(4) Right Engine Thrust Reverser PRI Cont

(5) Right Engine Thrust Reverser Sec Cont

(l) Supply electrical power.

(m) Remove the pressure from the left (right) hydraulic system.

B. Do the Thrust Reverser Sync Lock Test.

(1) Move and hold the manual unlock lever on the center actuator on both thrust reverser sleeves to the unlock position.

(2) Make sure the thrust reverser sleeves did not move.

(3) Move the left (right) reverser thrust lever up and rearward to the idle detent position.

(4) Make sure both thrust reverser sleeves move aft (approximately 0.15 to 0.25 inch).

(5) Release the manual unlock lever on the center actuators.

*Warning:* Make sure all persons and equipment are clear of the area around the Thrust Reverser. When you apply hydraulic pressure the Thrust Reverser will extend and can cause injuries to persons or damage to equipment.

(6) Pressurize the left (right) hydraulic system.

(7) Make sure the thrust reverser extends.

(8) Move the left (right) reverser thrust lever to the fully forward and down position to retract the thrust reverser.

C. Put the Airplane Back to its Usual Condition.

(1) Remove hydraulic pressure.

(2) Close the left and right fan cowls.

(3) Close the Auto Speedbrake circuit breaker on the P11 panel.

(4) Remove electrical power if it is not necessary.

(5) Return the EEC Maint Power switch or the EEC Power L and EEC Power R switches to the Normal position.

D. Repeat the Thrust Reverser Sync Lock Test on the other engine."

(k) Installation of the sync lock, as required by paragraph (i) of this AD, constitutes terminating action for the requirements of paragraphs (f) through (h) of this AD.

### **Alternative Methods of Compliance (AMOCs)**

(l)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) We approve the following for the corresponding requirements of this AD: AMOCs approved previously in accordance with AD 91-20-09, amendment 39-8043; AD 94-01-10, amendment 39-8792; and AD 94-01-10 R1, amendment 39-13247.

### **Material Incorporated by Reference**

(m) Except as otherwise specified in this AD, the actions must be done in accordance with Boeing Alert Service Bulletin 757-78A0027, dated September 9, 1991; Boeing Service Bulletin 757-78-0025, dated September 9, 1991; Boeing Document D630N002, "Boeing 757 Dispatch Deviation Guide," Revision 8, dated January 15, 1991; and Boeing Service Bulletin 757-78-0028, Revision 1, dated October 29, 1992, or Boeing Service Bulletin 757-78-0028, Revision 2, dated January 14, 1993; as applicable.

(1) The incorporation by reference of Boeing Service Bulletin 757-78-0028, Revision 1, dated October 29, 1992; and Boeing Service Bulletin 757-78-0028, Revision 2, dated January 14, 1993; was approved previously by the Director of the Federal Register as of March 3, 1994 (59 FR 4558, February 1, 1994).

(2) The incorporation by reference of Boeing Alert Service Bulletin 757-78A0027, dated September 9, 1991; Boeing Service Bulletin 757-78-0025, dated September 9, 1991; and Boeing Document D630N002, "Boeing 757 Dispatch Deviation Guide," Revision 8, dated January 15, 1991; was approved previously by the Director of the Federal Register as of September 16, 1991 (56 FR 46725, September 16, 1991). (The document number of Boeing Alert Service Bulletin 757-78A0027, dated September 9, 1991, was cited erroneously in the September 16, 1991, issue of the Federal Register as "757-78H0027." The document number of Boeing Service Bulletin 757-78-0025, dated September 9, 1991, was also cited erroneously in the September 16, 1991, issue of the Federal Register as "757-0025.")

(3) Contact Boeing Commercial Airplanes, PO Box 3707, Seattle, Washington 98124-2207, for copies of the service documents. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to

*[http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).*

Issued in Renton, Washington, on December 29, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-536 Filed 1-12-05; 8:45 am]

BILLING CODE 4910-13-P



**RAYTHEON AIRCRAFT COMPANY  
AIRWORTHINESS DIRECTIVE  
REVISION  
LARGE AIRCRAFT**

**98-20-38 R1 Raytheon Aircraft Company:** Amendment 39-13946; Docket No. FAA-2004-19078; Directorate Identifier 98-CE-17-AD.

**When Does This AD Become Effective?**

(a) This AD becomes effective on February 18, 2005.

**What Other ADs Are Affected by This Action?**

(b) This AD revises AD 98-20-38, Amendment 39-10806.

**What Airplanes Are Affected by This AD?**

(c) This AD affects the following airplane models, all serial numbers, that are certificated in any category:

- (1) Beech 200 (A100-1 (U-21J)).
- (2) Beech 200C.
- (3) Beech 200CT.
- (4) Beech 200T.
- (5) Beech A200 (C-12A) or (C-12C).
- (6) Beech A200C (UC-12B).
- (7) Beech A200CT (C-12D), (FWC-12D), (RC-12D), (C-12F), (RC-12G), (RC-12H), (RC-12K), or (RC-12P).
- (8) B200CT.
- (9) B200T.

**Note 1:** The actions of AD 96-09-13 are required for the Beech Models B200 and B200C airplanes.

**What Is the Unsafe Condition Presented in This AD?**

(d) The actions specified in this AD are intended to minimize the potential hazards associated with operating these airplanes in severe icing condition by providing more clearly defined procedures and limitations.

**What Must I Do To Address This Problem?**

(e) Within 30 days after November 4, 1998 (the effective date of AD 98-20-38), do the requirements of paragraphs (e)(1) and (e)(2) of this AD, unless already accomplished.

**Note 2:** Operators should initiate action to notify and ensure that flight crewmembers are apprised of this change.

(1) Revise the FAA-approved Airplane Flight Manual (AFM) by incorporating the following into the Limitations Section of the AFM. This may be accomplished by inserting a copy of this AD in the AFM.

### **"Warning**

Severe icing may result from environmental conditions outside of those for which the airplane is certificated. Flight in freezing rain, freezing drizzle, or mixed icing conditions (supercooled liquid water and ice crystals) may result in ice build-up on protected surfaces exceeding the capability of the ice protection system, or may result in ice forming aft of the protected surfaces. This ice may not be shed using the ice protection systems, and may seriously degrade the performance and controllability of the airplane.

- During flight, severe icing conditions that exceed those for which the airplane is certificated shall be determined by the following visual cues. If one or more of these visual cues exists, immediately request priority handling from Air Traffic Control to facilitate a route or an altitude change to exit the icing conditions.

–Unusually extensive ice accumulation on the airframe and windshield in areas not normally observed to collect ice.

–Accumulation of ice on the upper surface of the wing, aft of the protected area.

–Accumulation of ice on the engine nacelles and propeller spinners farther aft than normally observed.

- Since the autopilot, when installed and operating, may mask tactile cues that indicate adverse changes in handling characteristics, use of the autopilot is prohibited when any of the visual cues specified above exist, or when unusual lateral trim requirements or autopilot trim warnings are encountered while the airplane is in icing conditions.

- All wing icing inspection lights must be operative prior to flight into known or forecast icing conditions at night. [Note: This supersedes any relief provided by the Master Minimum Equipment List (MMEL).]"

(2) Revise the FAA-approved AFM by incorporating the following into the Normal Procedures Section of the AFM. This may be accomplished by inserting a copy of this AD in the AFM.

### **"The Following Weather Conditions May Be Conducive to Severe In-Flight Icing**

- Visible rain at temperatures below 0 degrees Celsius ambient air temperature.
- Droplets that splash or splatter on impact at temperatures below 0 degrees Celsius ambient air temperature.

### **Procedures for Exiting the Severe Icing Environment**

These procedures are applicable to all flight phases from takeoff to landing. Monitor the ambient air temperature. While severe icing may form at temperatures as cold as -18 degrees Celsius, increased vigilance is warranted at temperatures around freezing with visible moisture present. If the visual cues specified in the Limitations Section of the AFM for identifying severe icing conditions are observed, accomplish the following:

- Immediately request priority handling from Air Traffic Control to facilitate a route or an altitude change to exit the severe icing conditions in order to avoid extended exposure to flight conditions more severe than those for which the airplane has been certificated.
- Avoid abrupt and excessive maneuvering that may exacerbate control difficulties.
- Do not engage the autopilot.
- If the autopilot is engaged, hold the control wheel firmly and disengage the autopilot.
- If an unusual roll response or uncommanded roll control movement is observed, reduce the angle-of-attack.
- Do not extend flaps when holding in icing conditions. Operation with flaps extended can result in a reduced wing angle-of-attack, with the possibility of ice forming on the upper surface further aft on the wing than normal, possibly aft of the protected area.
- If the flaps are extended, do not retract them until the airframe is clear of ice.
- Report these weather conditions to Air Traffic Control."

(f) As an alternative method of compliance to the actions required by paragraph (e)(2) of this AD, revise the Abnormal Procedures Section or Emergency Procedures Section of the AFM instead of the Normal Procedures section of the AFM. Insert the information presented in paragraph (e)(2) of this AD into the applicable AFM section.

(g) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may incorporate the AFM revisions required by this AD. Enter this information into the aircraft records showing compliance with this AD following section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

#### **May I Request an Alternative Method of Compliance?**

(h) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Mr. Paul Pellicano, Aerospace Engineer (Icing Specialist), Atlanta Aircraft Certification Office, FAA, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6064; facsimile: (770) 703-6097.

#### **May I Get Copies of the Documents Referenced in This AD?**

(i) You may view the AD docket at the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC, or on the Internet at <http://dms.dot.gov>.

Issued in Kansas City, Missouri, on January 11, 2005.  
 Michael K. Dahl,  
 Acting Manager, Small Airplane Directorate, Aircraft Certification Service.  
 [FR Doc. 05-895 Filed 1-18-05; 8:45 am]  
 BILLING CODE 4910-13-P

## **BW 2005-02**

### **BOEING AIRWORTHINESS DIRECTIVE LARGE AIRCRAFT**

**2005-01-12 Boeing:** Amendment 39-13936. Docket 2003-NM-166-AD.

**Applicability:** Model 757-200, -200PF, and -200CB series airplanes, line numbers 1 through 979 inclusive; certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent a flap skew due to insufficient secondary load path of the ballscrew of the trailing edge flaps in the event that the primary load path fails, which could result in possible loss of a flap and reduced controllability of the airplane, accomplish the following:

#### **Inspection and Corrective Action**

(a) Within 48 months after the effective date of this AD, do an inspection of the ballscrews of the trailing edge flap system to find their part numbers (P/N). If the P/N of the ballscrew is S251N401-5 (Thomson Saginaw P/N 7820921) or S251N401-9 (Thomson Saginaw P/N 7821341), within 48 months after the effective date of this AD, replace the ballscrew with a new, serviceable, or modified ballscrew, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-27A0139, dated June 16, 2003.

#### **Parts Installation**

(b) As of the effective date of this AD, no person may install a trailing edge flap ballscrew, P/N S251N401-5 (Thomson Saginaw P/N 7820921) or S251N401-9 (Thomson Saginaw P/N 7821341), on any airplane.

#### **Alternative Methods of Compliance**

(c) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

#### **Incorporation by Reference**

(d) Unless otherwise specified in this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin 757-27A0139, dated June 16, 2003. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

#### **Effective Date**

(e) This amendment becomes effective on February 14, 2005.

Issued in Renton, Washington, on December 29, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-281 Filed 1-7-05; 8:45 am]

BILLING CODE 4910-13-P

**BW 2005-02**

**BOEING  
AIRWORTHINESS DIRECTIVE  
LARGE AIRCRAFT**

**2005-01-13 Boeing:** Amendment 39-13938. Docket No. FAA-2005-20010; Directorate Identifier 2003-NM-224-AD.

**Effective Date**

(a) This airworthiness directive (AD) becomes effective January 28, 2005.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to Boeing Model 767-300 series airplanes, certificated in any category; as listed in Boeing Alert Service Bulletin 767-26A0127, dated July 17, 2003.

**Unsafe Condition**

(d) This AD was prompted by a report of the failure of the engine fire shutoff switch in the engine fire control module. The Federal Aviation Administration is issuing this AD to prevent mineral build-up on the auxiliary power unit (APU) and engine fire shutoff switches, which could lead to the switches failing to discharge fire suppressant to the affected fire zone and result in an uncontrolled engine or APU fire and consequent loss of the airplane.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Service Bulletin Reference**

(f) The term "service bulletin," as used in this AD, means the Accomplishment Instructions of Boeing Alert Service Bulletin 767-26A0127, dated July 17, 2003.

**Initial and Repetitive Functional Tests**

(g) At the later of the compliance times specified in paragraphs (g)(1) and (g)(2) of this AD, do a functional test of the APU and engine fire shutoff switches, in accordance with the service bulletin. Repeat the functional test thereafter at intervals not to exceed 18 months.

(1) Within 18 months since the date of issuance of the original Airworthiness Certificate or the original Export Certificate of Airworthiness.

(2) Within 90 days after the effective date of this AD.

### **Corrective Action for Failure of a Fire Shutoff Switch**

(h) If any APU or engine fire shutoff switch fails during any functional test required by paragraph (g) or (k) of this AD, before further flight, replace the switch with a new or serviceable switch, in accordance with the service bulletin. Repeat the switch replacement thereafter at intervals not to exceed 36 months.

### **Initial and Repetitive Replacements of Fire Shutoff Switches**

(i) Within 18 months after the effective date of this AD, replace all APU and engine fire shutoff switches that have not been previously replaced in accordance with paragraph (h) of this AD with new or serviceable switches, in accordance with the service bulletin. Repeat the switch replacement thereafter at intervals not to exceed 36 months.

### **Optional Terminating Action: Deactivation of Humidifier**

(j) Accomplishment of the actions specified in paragraphs (j)(1) and (j)(2) of this AD, terminates the repetitive requirements of paragraphs (g), (h), and (i) of this AD, except as provided by paragraph (k) of this AD.

(1) Deactivate the Lucas humidifier, part number (P/N) M01AA0101, M01AB0101, M01AB0102, or M01AB0103, in accordance with the service bulletin.

(2) Before further flight following the deactivation specified in paragraph (j)(1) of this AD, replace all APU and engine fire shutoff switches with new or serviceable switches, in accordance with the service bulletin.

### **Reactivation of Lucas Humidifier**

(k) For any airplane on which Lucas humidifier, P/N M01AA0101, M01AB0101, M01AB0102, or M01AB0103, is reactivated after the effective date of this AD: Do the actions required by paragraphs (k)(1) and (k)(2) of this AD at the specified compliance times.

(1) Within 18 months after reactivating the humidifier, and thereafter at intervals not to exceed 18 months, do the functional tests required by paragraph (g) of this AD.

(2) Within 36 months after reactivating the humidifier, and thereafter at intervals not to exceed 36 months, replace all APU and engine fire shutoff switches that have not been previously replaced in accordance with paragraph (h) of this AD. Do the replacements in accordance with paragraph (i) of this AD.

### **Alternative Methods of Compliance (AMOC)**

(l) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

**Material Incorporated by Reference**

(m) You must use Boeing Alert Service Bulletin 767-26A0127, dated July 17, 2003, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies of the document from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. You can review copies at the Docket Management Facility office, U.S. Department of Transportation, 400 Seventh Street SW, room PL-401, Nassif Building, Washington, DC; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on December 29, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-538 Filed 1-12-05; 8:45 am]

BILLING CODE 4910-13-P



**BW 2005-02**

**ROLLS-ROYCE PLC  
AIRWORTHINESS DIRECTIVE  
ENGINE  
LARGE AIRCRAFT**

**2005-01-15 Rolls-Royce plc:** Amendment 39-13940. Docket No. 2001-NE-17-AD. Supersedes AD 2002-11-08, Amendment 39-12769.

**Effective Date**

(a) This AD becomes effective January 28, 2005.

**Affected ADs**

(b) This AD supersedes AD 2002-11-08, Amendment 39-12769.

**Applicability**

(c) This AD applies to Rolls-Royce plc (RR) RB211 Trent 875, 877, 884, 884B, 892, 892B, and 895 series turbofan engines with low pressure compressor (LPC) fan blades, part numbers (P/Ns) FK30838, FK30840, FK30842, FW12960, FW12961, FW12962, and FW13175, installed. These engines are installed on, but not limited to, Boeing Company 777 series airplanes.

**Unsafe Condition**

(d) This AD results from a report of a cracked fan blade found before the blade reached the initial inspection threshold of AD 2002-11-08. This AD also results from the need to reduce a repetitive inspection compliance time due to potential breakdown of blade coating and lubrication on certain blades. We are issuing this AD to prevent multiple LPC fan blade failures due to cracks, which could result in uncontained engine failure and possible damage to the airplane.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

(f) Ultrasonic-inspect and disposition the dovetail roots of LPC fan blades, P/Ns FK30838, FK30840, FK30842, FW12960, FW12961, FW12962, and FW13175, that are removed from the engine, using 3.A.(1) through 3.A.(5) or, for blades that are not removed from the engine, using 3.B.(1) through 3.B.(5) of the Accomplishment Instructions of RR Alert Service Bulletin (ASB) No. RB.211-72-AD344, Revision 7, dated March 12, 2004, as follows:

(1) For blades P/Ns FK30838, FK30840, and FK30842, that have not been relubricated during any interval exceeding 600 cycles-since-new (CSN) or cycles-since-rework (CSR) using either RR ASB No. RB.211-72-AD344 or No. RB.211-72-D347, inspect as specified in paragraph (f) of this AD and within the compliance times specified in the following Table 1:

**TABLE 1.—COMPLIANCE TIMES FOR BLADES P/NS FK30838, FK30840, AND FK30842**

Engine series	Boeing 777 series	Airplane maximum gross weight (times 1,000 pounds)	Initial Inspection CSN	Repetitive Inspection (cycles-since-last-inspection) (CSLI)
(i) –884B, –892	–300	(A) 660 and 632.5	600	80
		(B) 580	2,000	600
(ii) –884, –892, –892B, and –895	–200	(A) 632.5 and 648	1,200	100
		(B) 656	600	80
		(C) 555	2,000	600
(iii) –875	–200	535	2,000	600
(iv) –877	–200	545	2,000	600

(2) For blades P/Ns FK30838, FK30840, and FK30842, that have been relubricated at intervals not exceeding 600 CSN or CSR using either RR ASB No. RB.211-72-AD344 or SB RB.211-72-D347, inspect as specified in paragraph (f) of this AD and within the compliance times specified in the following Table 2:

**TABLE 2.—COMPLIANCE TIMES FOR BLADES P/NS FK30838, FK30840, AND FK30842**

Engine series	Boeing 777 series	Airplane maximum gross weight (times 1,000 pounds)	Initial Inspection CSN	Repetitive Inspection CSLI
(i) –884B, 892	–300	(A) 660 and 632.5	600	80
		(B) 580	2,400	600
(ii) 884, –892, –892B, and –895	–200	(A) 632.5 and 648	1,200	100
		(B) 656	600	80
		(C) 555	2,400	600
(iii) –875;	–200	535	2,400	600
(iv) –877	–200	545	2,400	600

(3) For blades P/Ns FW12960, FW12961, FW12962, and FW13175, either new or reworked to that configuration at greater than 600 CSN or since previous rework, or that have not been relubricated during any interval exceeding 600 CSN or CSR using either RR ASB No. RB.211-72-AD344 or RB.211-72-D347 requirements, inspect as specified in paragraph (f) of this AD and within the compliance times specified in the following Table 3:

**TABLE 3.—COMPLIANCE TIMES FOR BLADES P/NS FW12960, FW12961, FW12962, AND FW13175**

Engine series	Boeing 777 series	Airplane maximum gross weight (times 1,000 pounds)	Initial Inspection CSN	Repetitive Inspection CSLI
(i) –884B, –892	–300	(A) 660 and 632.5	600	100
		(B) 580	2,000	600
(ii) –884, –892, –892B, and –895	–200	(A) 632.5 and 648	1,200	125
		(B) 656	600	100
		(C) 555	2,000	600
(iii) –875	–200	535	2,000	600
(iv) –877	–200	545	2,000	600

(4) For blades P/Ns FW12960, FW12961, FW12962, and FW13175, either new or reworked to that configuration at fewer than 600 CSN or since previous rework, and that have been relubricated at intervals not exceeding 600 CSN using either RR ASB No. RB.211-72-AD344 or SB No. RB.211-72-D347, inspect as specified in paragraph (f) of this AD and within the compliance times specified in the following Table 4:

**TABLE 4.—COMPLIANCE TIMES FOR BLADES P/NS FW12960, FW12961, FW12962, AND FW13175**

Engine series	Boeing 777 series	Airplane maximum gross weight (times 1,000 pounds)	Initial Inspection CSN	Repetitive Inspection CSLI
(i) -884B, -892	-300	(A) 660 and 632.5	600	100
		(B) 580	2,400	1,200
(ii) -884, -892, -892B, and -895	-200	(A) 632.5 and 648	2,400	125
		(B) 656	600	100
		(C) 535	2,400	1,200
(iii) -875	-200	535	2,400	1,200
(iv) -877	-200	545	2,400	600

(g) When engines containing blades P/Ns FK30838, FK30840, FK30842, FW12960, FW12961, FW12962, and FW13175 are moved from one gross weight category to another, the inspection schedule that is applicable to the higher gross weight category must be used.

### Terminating Action

(h) As terminating action to the repetitive inspection requirements of this AD, at the next shop visit when the fan blades are removed for repair or overhaul, but no later than December 31, 2009:

(1) Replace LPC fan blades P/Ns FK30838, FK30840, FK30842, FW12960, FW12961, FW12962, or FW13175 with a complete set of LPC fan blades that have been reworked, relubricated, and remarked using RR SB No. RB.211-72-D672, dated February 1, 2002; or;

(2) Replace LPC fan blades P/Ns FK30838, FK30840, FK30842, FW12960, FW12961, FW12962, or FW13175 with a complete set of new LPC fan blades that feature additional blade root processing requirements found in RR SB No. RB.211-72-D672, dated February 1, 2002.

### Previous Credit

(i) Previous credit is allowed for initial inspections of fan blades that were done using RR ASB No. RB.211-72-AD344, Revision 4, dated March 15, 2002, Revision 5, dated June 20, 2003, Revision 6, dated February 27, 2004, or Revision 7, dated March 12, 2004, before the effective date of this AD.

### Alternative Methods of Compliance

(j) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

## Material Incorporated by Reference

(k) You must use the Rolls-Royce plc service information specified in Table 5 of this AD to perform the blade inspections and replacements required by this AD. The Director of the Federal Register approved the incorporation by reference of the documents listed in Table 5 of this AD in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You can get a copy from Rolls-Royce plc, P.O. Box 31, Derby DE24 6BJ, UK; telephone 44 (0) 1332 242424; fax 44 (0) 1332 249936. You may review copies at the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2001-NE-17-AD, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to:

[http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html). Table 5 follows:

**TABLE 5.—INCORPORATION BY REFERENCE**

<b>Service Bulletin No.</b>	<b>Page</b>	<b>Revision</b>	<b>Date</b>
RB.211-72-AD344 Total Pages: 11	ALL	7	March 12, 2004.
RB.211-72-AD344, Appendices 1 through 5 Total Pages: 18	ALL	7	March 12, 2004.
RB.211-72-D672 Total Pages: 24	ALL	Original	February 1, 2002.

## Related Information

(l) Civil Aviation Authority (CAA) airworthiness directive G-2004-0008, dated April 29, 2004, also addresses the subject of this AD.

Issued in Burlington, Massachusetts, on January 3, 2005.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 05-485 Filed 1-12-05; 8:45 am]

BILLING CODE 4910-13-P

**BW 2005-02**

**ROLLS-ROYCE PLC  
AIRWORTHINESS DIRECTIVE  
ENGINE  
LARGE AIRCRAFT**

**2005-01-16 Rolls-Royce plc:** Amendment 39-13941. Docket No. 2000-NE-05-AD. Supersedes AD 2001-16-05, Amendment 39-12373.

**Effective Date**

(a) This AD becomes effective January 28, 2005.

**Affected ADs**

(b) This AD supersedes AD 2001-16-05, Amendment 39-12373.

**Applicability**

(c) This AD applies to Rolls-Royce plc (RR) RB211 Trent 768-60, Trent 772-60, and Trent 772B-60 turbofan engines with low pressure compressor (LPC) fan blade part numbers FK22580, FK23411, FK25441, and FK25968 installed. These engines are installed on, but not limited to, Airbus A330 series airplanes.

**Unsafe Condition**

(d) This AD supersedure results from analysis of flight data returned to RR, that shows a need for consistent inspection thresholds for all engine models. We are issuing this AD to prevent possible multiple LPC fan blade failures, which could result in an uncontained engine failure and damage to the airplane.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

**Initial Ultrasonic Inspection**

(f) Perform an initial ultrasonic inspection of the LPC fan blade dovetail roots using Method A (paragraphs 3.A.(1) through 3.A.(8); blades removed from engine) of Accomplishment Instructions of RR Mandatory Service Bulletin (MSB) No. RB.211-72-C878, Revision 7, dated December 5, 2003, as follows:

- (1) Inspect before accumulating 1,100 cycles-since-new (CSN) on the fan blades; or
- (2) For fan blades that have accumulated more than 800 CSN on the effective date of this AD that have not been previously inspected, inspect within 300 cycles-in-service (CIS) from the effective date of this AD or within 2,000 CSN, whichever occurs first.

## Repetitive Ultrasonic Inspections

(g) Perform repetitive inspections of the LPC fan blades using Method A, or Method B (paragraphs 3.B.(1) through 3.B.(5); blades not removed from the engine) of the Accomplishment Instructions of RR MSB No. RB.211-72-C878, Revision 7, dated December 5, 2003, as follows:

- (1) Inspect within 300 CIS since-last-inspected with Method A of the SB; or
- (2) Inspect within 250 CIS since-last-inspected with Method B of the SB.

## Alternative Methods of Compliance

(h) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

## Material Incorporated by Reference

(i) You must use the Rolls-Royce plc service information specified in Table 1 of this AD to perform the blade inspections and replacements required by this AD. The Director of the Federal Register approved the incorporation by reference of the documents listed in Table 1 of this AD in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You can get a copy from Rolls-Royce plc, PO Box 31, Derby DE24 6BJ, UK; telephone 44 (0) 1332 242424; fax 44 (0) 1332 249936. You may review copies at the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-NE-05-AD, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to:

[http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html). Table 1 follows:

**TABLE 1.—INCORPORATION BY REFERENCE**

<b>Mandatory service bulletin No.</b>	<b>Page</b>	<b>Revision</b>	<b>Date</b>
RB.211-72-C878 Total Pages: 9	All	7	December 5, 2003.
RB.211-72-C878, Appendix 1 Total Pages: 4	All	7	December 5, 2003.
RB.211-72-C878, Appendix 2 Total Pages: 5	All	7	December 5, 2003.

## Related Information

(j) United Kingdom Civil Aviation Authority airworthiness directive 003-11-99 also addresses the subject of this AD.

Issued in Burlington, Massachusetts, on January 4, 2005.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 05-484 Filed 1-12-05; 8:45 am]

BILLING CODE 4910-13-P

**RAYTHEON AIRCRAFT COMPANY  
AIRWORTHINESS DIRECTIVE  
LARGE AIRCRAFT**

**CORRECTION:** There are typos in the superseded AD# reference in the Compliance section of AD 2005-01-18, paragraph (e), page 2943, published today, January 19, 2005 in the Federal Register (FR). The superseded AD# of AD 2005-01-18 should be 93-25-07. GPO (Government Printing Office) will issue a correction to the FR. We've corrected this copy and added *revision marks* to the "pdf" copy for clarity.

**2005-01-18 Raytheon Aircraft Company:** Amendment 39-13943; Docket No. 2004-CE-01-AD.

**When Does This AD Become Effective?**

- (a) This AD becomes effective on March 1, 2005.

**What Other ADs Are Affected by This Action?**

- (b) This AD supersedes AD 93-25-07, Amendment 39-8773.

**What Airplanes Are Affected by This AD?**

- (c) This AD affects the following Beech airplane models and serial numbers that are certificated in any category:

Model	Serial Nos.
(1) A100-1 (U-21J)	BB-3 through BB-5
(2) 200 and B200	BB-2 and BB-6 through BB-1462.
(3) A200 (C-12A) and A200 (C-12C).	BC-1 through BC-75 and BD-1 through BD-30.
(4) A200C (UC-12B)	BJ-1 through BJ-66.
(5) A200CT (C-12D).	BP-1, BP-22, and BP-24 through BP-51.
(6) A200CT (FWC-12D).	BP-7 through BP-11.
(7) A200CT (RC-12D).	GR-1 through GR-13.
(8) A200CT (C-12F)	BP-52 through BP-63.
(9) A200CT (RC-12G).	FC-1 and FC-3.
(10) A200CT (RC-12H).	GR-14 through GR-19.
(11) A200CT (RC-12K).	FE-1 through FE-9.
(12) A200CT (RC-12P).	FE-10 through FE-24.
(13) A200CT (RC-12K).	FE-25 through FE-31.
(14) 200C and B200C	BL-1 through BL-72 and BL-124 through BL-138.
(15) 200CT	BN-1 through BN-4 and B200CT.
(16) 200T	BT-1 through BT-38 and B200T.
(17) B200C (C-12F)	BL-73 through BL-112 and BL-118 through BL-123.

(18) B200C (C-12F)	BP-64 through BP-71.
(19) B200C (UC-12F)	BU-1 through BU-10.
(20) B200C (UC-12M).	BV-1 through BV-12.
(21) B200CT	FG-1 and FG-2.
(22) 300	FA-1 through FA-228.
(23) 300	FF-1 through FF-19.
(24) B300	FL-1 through FL-103.
(25) B300C	FM-1 through FM-8.
(26) B300C	FN-1.

### What Is the Unsafe Condition Presented in This AD?

(d) As currently written, AD 93-25-07 allows continued flight if cracks are found in less than five fuselage stringers in the area of the rear pressure bulkhead. In 1996, FAA developed policy to not allow airplane operation when known cracks exist in primary structure, unless the ability to sustain limit and ultimate load with these cracks is proven. The fuselage stringers in the area of the rear pressure bulkhead are considered primary structure. This AD will bring the actions of AD 93-25-07 in compliance with current FAA policy. The actions specified in this AD are intended to detect and correct any cracked fuselage stringers in the rear pressure bulkhead area, which could result in structural damage to the fuselage. This damage could lead to failure of the fuselage with potential loss of control of the airplane.

### What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
<p>(1) For <i>airplanes that have been known cracks that exist in any of the aft fuselage stringer locations (No. 5 through No. 11 on both the left-hand and right-hand sides)</i>. Either modify or incorporate repairs as specified below. These cracks could have been detected through compliance with AD 93-25-07 and/or Raytheon Mandatory Service Bulletin SB 53-2472, any revision level:</p> <p>(i) Incorporate the applicable modification kit or kits as specified in Raytheon Mandatory Service Bulletin SB 53-2472, Rev. 4, Issued: June, 1993, Revised: July, 2003; or</p> <p>(ii) Incorporate external doubler repairs on all aft fuselage stringer locations (No. 5 through No. 11 on both the left-hand and right-hand sides)</p>	<p><i>If airplane has less than five known cracked stringers:</i> Within 25 cycles after March 1, 2005 (the effective date of this AD), unless already done. If cycles are unknown, then you may divide hours time-in-service (TIS) by .75 (<math>18.75 \text{ hours TIS} \div .75 = 25 \text{ cycles}</math>). <i>If airplane has five or more known cracked stringers:</i> Before further flight after March 1, 2005 (the effective date of this AD), unless already done. AD 93-25-07 already required this.</p>	<p>Incorporate the modification kit(s) following The procedures in Raytheon Mandatory Service Bulletin SB 53-2472, Rev. 4, Issued: June, 1993, Revised: July, 2003. Incorporate the external doubler repairs following the procedures in the maintenance manual.</p>



<p>(2) <i>For all airplanes that do not have either themodifications or repairs specified in paragraphs (e)(1)(i) and (e)(1)(ii) of this AD incorporated in all aft fuselage stringer locations (No. 5 through No. 11 on both the left-hand and right-hand sides):</i> Inspect these aft fuselage stringers. If sealant covers the stringers, you must remove it to facilitate the required inspections and then reapplied. You may terminate the repetitive inspections when all aft fuselage stringer locations (No. 5 through No. 11 on both the left-hand and right-hand sides) are modified.</p>	<p><i>For airplanes affected by AD 93–25–07:</i> Initially inspect at the next inspection interval required by AD 93–25–07. Repetitively inspect thereafter at intervals not to exceed 500 cycles. If cycles are unknown, then you may divide TIS by .75 (375 hours TIS ÷ .75 = 500 cycles). <i>For airplanes not affected by AD 93–25–07:</i> Initially inspect upon accumulating 2,500 cycles on the fuselage or within the next 25 cycles after March 1, 2005 (the effective date of this AD), whichever occurs later, unless already done. Repetitively inspect thereafter at intervals not to exceed 500 cycles. If cycles are unknown, then you may divide hours TIS by .75 (1,875 hours TIS ÷ .75 = 2,500 cycles; 375 hours TIS ÷ .75 = 500 cycles; and 18.75 hours TIS ÷ .75 = 25 cycles).</p>	<p>Inspect following the procedures in Raytheon Mandatory Service Bulletin SB 53–2472. Rev. 4, Issued: June, 1993, Revised: July, 2003.</p>
<p>(3) If any cracks are found during any inspection required by this AD, do one of the following:</p> <p>(i) Incorporate the applicable modification kit or kits as specified in Raytheon Mandatory Service Bulletin SB 53–2472, Rev. 4, Issued: June, 1993, Revised: July, 2003; or</p> <p>(ii) Incorporate external doubler repairs on all aft fuselage stringer locations (No. 5 through No. 22 on both the left-hand and right-hand sides)</p>	<p><i>If less than five cracked stringers are found:</i> Within 25 cycles after March 1, 2005 (the effective date of this AD), unless already done. If cycles are unknown, then you may divide hours TIS by .75 (18.75 hours TIS ÷ .75 = 25 cycles). <i>If five or more cracked stringers are found:</i> Before further flight after any inspection where five cracked stringers are found, unless already done.</p>	<p>Incorporate the modification kit(s) following The procedures in Raytheon Mandatory Service Bulletin SB 53–2472, Rev. 4, Issued: June, 1993, Revised: July, 2003. Incorporate the external doubler repairs following the procedures in the maintenance manual.</p>

### May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Wichita Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Steven E. Potter, Aerospace Engineer, Wichita Aircraft Certification Office (ACO), FAA, 1801 Airport Road, Wichita, Kansas 67209; telephone: (316) 946-4124; facsimile: (316) 946-4107.

**Does This AD Incorporate Any Material by Reference?**

(g) You must do the actions required by this AD following the instructions in Raytheon Mandatory Service Bulletin SB 53-2472, Rev. 4, Issued: June, 1993, Revised: July, 2003. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You may get a copy from Raytheon Aircraft Company, 9709 E. Central, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You may review copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on January 7, 2005.

James E. Jackson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-716 Filed 1-18-05; 8:45 am]

BILLING CODE 4910-13-P

**BW 2005-02**

**GARMIN INTERNATIONAL INC.  
AIRWORTHINESS DIRECTIVE  
APPLIANCE  
LARGE AIRCRAFT**

**2005-01-19 GARMIN International Inc.:** Amendment 39-13944; Docket No. FAA-2004-18743; Directorate Identifier 2004-CE-23-AD.

**When Does This AD Become Effective?**

(a) This AD becomes effective on February 23, 2005.

**What Other ADs Are Affected by This Action?**

(b) This AD supersedes AD 2004-10-15, Amendment 39-13645.

**What Airplanes Are Affected by This AD?**

(c) This AD affects GARMIN International Inc. GTX 33, GTX 33D, GTX 330, and GTX 330D Mode S transponders that include software versions 3.00, 3.01, 3.02, 3.04, or 3.05 that are installed on, but not limited to, the following airplanes, certificated in any category:

<b>Manufacturer</b>	<b>Model</b>
(1) Aermacchi S.p.A	S.205-18/F, S.205-18/R, S.205-20/R, S.205-22/R, S208, S.208A, F.260, F.260B, F.260C, F.260D, F.260E, F.260F, S.211A.
(2) Aeronautica Macchi S.p.A	AL 60, AL 60-B, AL 60-F5, AL 60-C5, AM-3.
(3) Aerostar Aircraft Corporation	PA-60-600 (Aerostar 600), PA-60-601 (Aerostar 601), PA-60-601P (Aerostar 601P), PA-60-602P (Aerostar 602P), PA-60-700P (Aerostar 700P), 360, 400.
(4) Alexandria Aircraft, LLC	14-19, 14-19-2, 14-19-3, 14-19-3A, 17-30, 17-31, 17-31TC, 17-30A, 17-31A, 17-31ATC
(5) Alliance Aircraft Group LLC	15A, 20, H-250, H-295 (USAFU-10D), HT-295, H391 (USAFYL-24), H391B, H-395 (USAFU-28A or U-10B), H-395A, H-700, H-800, HST-550, HST-550A (USAF AU-24A), 500.
(6) American Champion Aircraft Corp	402, 7GCA, 7GCB, 7KC, 7GCBA, 7GCAA, 7GCBC, 7KCAB, 8KCAB, 8GCBC.
(7) Sky International Inc	A-1, A-1A, A-1B, S-1S, S-1T, S-2, S-2A, S-2S, S-2C.
(8) B-N Group Ltd	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-8, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, BN-2T-4R, BN-2A MK.III, BN2A MK. III-2, BN2A MK. 111-3.
(9) Bellanca	14-13, 14-13-2, 14-13-3, 14-13-3W.
(10) Bombardier Inc	(Otter) DHC-3, DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300.

(11) Cessna Aircraft Company	170, 170A, 170B, 172, 172A, 172B, 172C, 172D, 172E, 172F (USAF T-41A), 172G, 172H (USAF T041A), 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172R, 172S, 172RG, P172D, R172E (USAF T-41 B) (USAF T-41 C AND D), R172F (USAF T-41 D), R175G, R172H (USAF T-41 D), R172J, R172K, 175, 175A, 175B, 175C, 177, 177A, 177B, 177RG, 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, 182S, 182T, R182, T182, TR182, T182T, 185, 185A, 185B, 185C, 185D, 185E, A185E, A185F, 190, (LC-126A, B, C) 195, 195A, 195B, 210, 210A, 210B, 210C, 210D, 210E, 210F, T210F, 210G, T210G, 210H, T210H, 210J, T210J, 210K, T210K, 210L, T210L, 210M, T210M, 210N, P210N, T210N, 210R, P210R, T210R, 210-5 (205), 210-5A (205A), 206, P206, P206A, P206B, P206C, P206D, P206E, TP206A, TP206B, TP206C, TU206D, TU206E, TU206F, TU206G, 206H, T206H, 207, 207A, T207, T207A, 208, 208A, 208B, 310, 310A (USAF U-3A), 310B, 310C, 310D, 310E (USAF U-3B), 310F, 310G, 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R, 320, 320A, 320B, 320C, 320D, 320E, 320F, 320-1, 335, 340, 340A, 336, 337, 337A (USAF 02B), 337B, T337B, 337C, 337E, T337E, T337C, 337D, T337D, M337B (USAF 02A), 337F, T337F, T337G, 337G, 337H, P337H, T337H, T337H-SP, 401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C, 425, 404, 406, 441.
(12) Cirrus Design Corporation	SR20, SR22.
(13) Commander Aircraft Company	112, 112TC, 112B, 112TCA, 114, 114A, 114B, 114TC.
(14) de Havilland Inc	DHC-2 Mk. I, DHC-2 Mk. II, DHC-2 Mk. III.
(15) Dynac Aerospace Corporation	(Volaire) 10, (Volaire) 10A, (Aero Commander) 100, (Aero Commander) 100A, (Aero Commander) 100-180.
(16) Diamond Aircraft Industries	DA 20-A1, DA20-C1, DA 40.
(17) Empresa Brasileira de Aeronautica S.A. EMBRAER.	EMB-110P1, EMB-110P2.
(18) Extra Flugzeugbau Gmbh	EA300, EA300L, EA300S, EA300/200, EA-400.
(19) Fairchild Aircraft Corporation	SA26-T, SA26-AT, SA226-T, SA226-AT, SA226-T(B), SA227-AT, SA227-TT, SA226-TC, SA227-AC (C-26A), SA227-CC, SA227-DC (C-26B).
(20) Global Amphibians, LLC	Colonial C-1, Colonial C-2, Lake LA-4, Lake LA-4A, Lake LA-4P, Lake LA-4-200, Lake Model 250.
(21) Grob-Werke	G115, G115A, G115B, G115C, G115C2, G115D, G115D2, G115EG, G120A.
(22) Lancair Company	LC40-550FG.

(23) LanShe Aerospace, LLC	MAC-125C, MAC-145, MAC-145A, MAC-145B.
(24) Learjet Inc.	23.
(25) Lockheed Aircraft Corporation	18.
(26) Luscombe Aircraft Corporation	11A, 11E.
(27) Maule Aerospace Technology, Inc	Bee Dee M-4, M-4, M-4C, M-4S, M-4T, M-4180C, M-4-180S, M-4-180T, M-4-210, M-4-210C, M-4-210S, M-4-210T, M-4-220, M-4-220S, M-4-220T, M-5-180C, M-5-200, M-5-210C, M-5-210TC, M-5-220C, M-5-235C, M-6-180, M-6-235, M-7-235, MX-7-235, MX-7-180, MX-7-420, MXT-7-180, MT-7-235, M-8-235, MX-7-160, MXT-7-160, MX-7-180A, MXT-7-180A, MX-7-180B, M-7-235B, M-7-235A, M-7-235C, MX-7-180C, M-7-260, MT-7-260, M-7-260C, M-7-420AC, MX-7-160C, MX-7-180AC, M-7-420A, MT-7-420.
(28) Mitsubishi Heavy Industries, Ltd	MU-2B-25, MU-2B-35, MU-2B-26, MU-2B-36, MU-2B-26A, MU-2B-36A, MU-2B-40, MU-2B-60, MU-2B, MU-2B-20, MU-2B-15.
(29) Mooney Airplane Company, Inc	M20, M20A, M20B, M20C, M20D, M20E, M20F, M20G, M20J, M20K, M20L, M20M, M20R, M20S, M22.
(30) Moravan a.s	Z-242L, Z-143L.
(31) Navion Aircraft Company, Ltd	NAVION, Navion (L-17A), Navion (L17B), Navion (L-17C), Navion B, Navion D, Navion E, Navion F, Navion G, Navion H.
(32) New Piper Aircraft, Inc	PA-12, PA-12S, PA-18, PA-18S, PA-18 "105" (Special), PA-18S "105" (Special), PA-18A, PA-18 "125" (Army L-21A), PA-18S "125," PA-18AS "125," PA-18 "135" (Army L-21B), PA-18A "135," PA-18S "135," PA-18 "150," PA-18A "150," PA-18S "150," PA-18AS "150," PA-19 (Army L-18B), PA-19S, PA-20, PA-20S, PA-20 "115," PA-20S "115," PA-20 "135," PA-20S "135," PA-22, PA-22-108, PA-22-135, PA-22S-135, PA-22-150, PA-22S-150, PA-22-160, PA-22S-160, PA-23, PA-23-160, PA-23-235, PA-23-250, PA-E23-250, PA-24, PA-24-250, PA-24-260, PA-24-400, PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-235, PA-28S-160, PA-28R-180, PA-28S-180, PA-28-181, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-28-201T, PA-28-236, PA-30, PA-39, PA-40, PA-31P, PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-31P-350, PA-32-260, PA-32-300, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301 (SP), PA-32R-301 (HP), PA-32R-301T, PA-32-301, PA-32-301T, PA-34-200, PA-34-200T, PA-34-220T, PA-42, PA-42-720, PA-42-1000, PA-42-720R, PA-44-180, PA-44-180T, PA-46-310P, PA-46-350P, PA-46-500TP.
(33) Ostmecklenburgische Flugzeugbau GmGH	OMF-100-160.

(34) Piaggio Aero Industries S.p.A	P-180.
(35) Pilatus Aircraft Ltd	PILATUS PC-12, PILATUS PC-12/45, PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PA-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, PC-6/C1-H2, PC-7.
(36) Prop-Jets, Inc	200, 200A, 200B, 200C, 200D, 400.
(37) Panstwowe Zaklady Lotnicze (PZL)	PZL-104 WILGA 80, PZL-104M WILGA 2000, PZL-WARSZAWA, PZL-KOLIBER 150A, PZL-KOLIBER 160A.
(38) PZL WSK/Mielec Obrsk	PZL M20 03, PZL M26 01.
(39) Raytheon	35-33, 35-A33, 35-B33, 35-C33, 35-C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A36TC, B36TC, 35, A35, B35, C35, D35, E35, F35, G35, 35R, F90, 76, 200, 200C, 200CT, 200T, A200, B200, B200C, B200CT, B200T, 300, 300LW, B300, B300C, 1900, 1900C, 1900D, A100-1 (U-21J), A200 (C-12A), A200 (C-12C), A200C (UC-12B), A200CT (C-12D), A200CT (FWC-12D), A200CT (RC-12D), A200CT (C-12F), A200CT (RC-12G), A200CT (RC-12H), A200CT (RC-12K), A200CT (RC-12P), A200CT (RC-12Q), B200C (C-12F), B200C (UC-12F), B200C (UC-12M), B200C (C-12R), 1900C (C-12J), 65, A65, A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 65-88, 65-A90, 70, B90, C90, C90A, E90, H90, 65-A90-1, 65-A90-2, 65-A90-3, 65-A90-4, 95, B95, B95A, D95A, E95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B (T-42A), 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A, 58P, 58PA, 58TC, 58TCA, 99, 99A, 99A (FACH), A99, A99A, B99, C99, 100, A100 (U-21F), A100A, A100C, B100, 2000, 3000, 390, 19A, B19, M19A, 23, A23, A23A, A23-19, A23-24, B23, C23, A24, A24R, B24R, C24R, 60, A60, B60, 18D, A18A, A18D, S18D, SA18A, SA18D, 3N, 3NM, 3TM, JRB-6, D18C, D18S, E18S, RC-45J (SNB-5P), E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J, UC-45J (SNB-5), 50 (L-23A), B50 (L-23B), C50, D50 (L-23E), D50A, D50B, D50C, D50E-5990, E50 (L-23D, RL-23D), F50, G50, H50, J50, 45 (YT-34), A45 (T-34A or B-45), D45 (T-34B).
(40) Rockwell International Corporation	BC-1A, AT-6 (SNJ-2), AT-6A (SNJ-3), AT-6B, AT-6C (SNJ-4), AT-6D (SNJ-5), AT-6F (SNF-6), SNJ-7, T-6G, NOMAD NA-260.
(41) Short Brothers & Harland Ltd	SC-7 Series 2, SC-7 Series 3.
(42) Slingsby Aviation Ltd	T67M260, T67M260-T3A.
(43) SOCAT-A Group Aerospatiale	TB9, TB10, TB20, TB21, TB200, TBM 700, M.S. 760, M.S. 760 A, M.S. 760 B, Rallye 100S, Rallye 150ST, Rallye 150T, Rallye 235E, Rallye 235C, MS 880B, MS 885, MS 894A, MS 893A, MS 892A-150, MS 892E-150, MS 893E, MS 894E, GA-7.
(44) Tiger Aircraft LLC	AA-1, AA-1A, AA-1B, AA-1C, AA-5, AA-5A, AA-5B, AG-5B.

(45) Twin Commander Aircraft Corporation	500, 500-A, 500-B, 500-U, 500-S, 520, 560, 560-A, 560-E, 560F, 680, 680E, 680F, 680FL, 680FL(P), 680T, 680V, 680W, 681, 685, 690, 690A, 690B, 690C, 690D, 695, 695A, 695B, 720, 700.
(46) Univair Aircraft Corporation	108, 108-1, 108-2, 108-3, 108-5.
(47) Vulcanair S.p.A	P68, P68B, P68C, P68C-TC, P68 "Observer," P68 "Observer 2," P68TC "Observer," AP68TP300 "Spartacus," AP68TP 600 "Viator".
(48) Zenair Ltd.	CH2000.

### What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of observations that the GTX 33/33D/330/330D may detect, from other airplanes, the S1 (suppression) interrogating pulse below the minimum trigger level (MTL) and, in some circumstances, not reply. The GTX 33/33D/330/330D should still reply even if it detects S1 interrogating pulses below the MTL. The actions specified in this AD are intended to prevent interrogating aircraft from possibly receiving inaccurate replies, due to suppression, from aircraft equipped with the GTX 33/33D/330/330D Mode S transponders when the pulses are below the minimum trigger level (MTL). Software Upgrade Versions 3.03 and 3.06 correct a TAS, TCAD, and TCAS I system "whisper-shout" problem that could potentially lead to the aircraft not being visible at certain ranges. TCAS II systems are not affected. The inaccurate replies could result in reduced vertical separation.

### What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
Install GTX 33/33D/330/330D Software Upgrade for transponders with software version 3.00, 3.01, 3.02, 3.04, 3.05 to at least version 3.06. If version 3.03 is already installed, no further action is required. This version is no longer available from Garmin. This AD does not apply to software versions past 3.05.	Install the software upgrade within 180 days after February 23, 2005 (the effective date of this AD), unless already accomplished.	Follow GARMIN Mandatory Software Service Bulletin No.: 0304, Rev B, dated June 12, 2003 accomplished. (Software Upgrade 3.03) or GARMIN Mandatory Software Service Bulletin No.: 0409, dated July 19, 2004 (Software Upgrade 3.06).

### May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Wichita Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Roger A. Souter, FAA, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: 316-946-4134; facsimile: 316-946-4107; email address: roger.souter@faa.gov.

**Does This AD Incorporate Any Material by Reference?**

(g) You must do the actions required by this AD following the instructions in GARMIN Mandatory Software Service Bulletin No.: 0304, Rev B, dated June 12, 2003 (Software Upgrade 3.03) or GARMIN Mandatory Software Service Bulletin No.: 0409, dated July 19, 2004 (Software Upgrade 3.06). The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get a copy of this service information, contact GARMIN International Inc. 1200 East 151st Street, Olathe, KS 66062; telephone: 913-397-8200. To review copies of this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html) or call (202) 741-6030. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2004-18743.

Issued in Kansas City, Missouri, on January 7, 2005.

James E. Jackson,  
Acting Manager, Small Airplane Directorate, Aircraft Certification Service.  
[FR Doc. 05-832 Filed 1-18-05; 8:45 am]  
BILLING CODE 4910-13-P